

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Inspector: Fadima

Marthoma Central School

Attingal / Varkala

1) Two Storeyed RCC Building
1 x 49.43 x 10.5 x 7.0

2) Three Storeyed Building including
Staircase

1 x 23.55 x 10.1 x 11.0

3) 2nd floor north west portion

concrete roof 1 x 10.05 x 6.9 x 3.0

Do. Verandha Portion Sheet 1 x 10.08 x 2.2

5. Period for which the certificate is issued

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

7. Any major defects noticed which will render the building unsafe in any manner

Nil.

8. Whether maintenance works have been done properly

Yes

9. Whether the structure is sound or not for conducting classes

The structure is sound to conduct classes
under normal wind and weather conditions. The inspection was done using naked eyes
no major tests was conducted.
separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 31/05/2025. and
found to be fit / unfit to conduct classes, for the period 2025 - 26. for the
reasons stated above.

Place: Cherunniyoor

Date: 31/05/2025.

Manager
MAR THOMA CENTRAL SCHOOL
CHERUNNIYOOR VARKALA

31/05/25
Assistant Executive Engineer (Seal)
Local Self Government Department
Varkala Block Panchayath
ASSISTANT ENGINEER
LID&EW
CHERUNNIYOOR G.P.

Principal
Mar Thoma Central School
Cherunniyoor, Varkala